









ASSEMBLING INSTRUCTION

CHESTER WORKING DESK 120
BLACK OAK




 D 12 X ∅12 MM X 10 MM	 E1 12 X ∅6 X 30 MM	 B 12 X ∅10 X 44 MM	 J3 16 X ∅6 MM X 13 MM	 AT 2 X ∅6 MM X 13 MM	 M3 18 X ∅5 MM X 24 MM
 Q FULL OVERLAY 2 X	 V8 2 X ∅19 MM	 U1 2 X 13 MM	 F 5 g 350 MM	 Z1 1 SET R1, R2, L1, L2	
 L1 ∅6 MM X 32 MM 4 X	 M6 ∅6 MM X 16 MM 24 X	 BU 1 X	 M9 ∅5 MM X 24 MM 8 X		




 x2 ±45 M 

M3	AT	B	J3	E1
Ø 6 MM X 13 MM 3 X	1 X	Ø 6 X 30 MM 1 X	Ø 10 X 44 MM 4 X	Ø 12 MM X 10 MM 4 X

1




2




03

E1	B	J3
Ø 12 MM X 10 MM 2 X	Ø 6 X 30 MM 2 X	Ø 10 X 44 MM 4 X



3




4




04

<p>M9</p>  <p>∅ 5 MM X 24 MM 8 X</p>	<p>M3</p>  <p>∅ 6 MM X 13 MM 2 X</p>	<p>B</p>  <p>∅ 6 X 30 MM 4 X</p>	<p>E1</p>  <p>∅ 12 MM X 10 MM 4 X</p>	<p>J3</p>  <p>∅ 10 X 44 MM 8 X</p>	<p>V8</p>  <p>1 X</p>	<p>U1</p>  <p>∅ 19 MM 1 X</p>	<p>M3</p>  <p>∅ 6 MM X 13 MM 9 X</p>	<p>AT</p>  <p>1 X</p>	<p>D</p>  <p>10 X</p>	<p>Q</p>  <p>FULL OVERLAY 2 X</p>
---	---	---	--	---	---	---	---	--	---	--


5




6



7



8



05

06

