






# ASSEMBLING INSTRUCTION

## KIVA SHOWCASE 1D




|   |  |  |   |   |   |
|---|--|--|---|---|---|
| BT16<br><br>6 X            | BU<br><br>1 X               | E1<br><br>Ø15 MM X 12 MM 24 X | B<br><br>Ø8 MM X 30 MM 29 X  | M1<br><br>Ø 4 MM X 5/8" 14 X | J3<br><br>Ø 12 MM X 1 3/4" 14 X |
| M<br><br>Ø 4 MM X 1/2" 2 X | D<br><br>Ø6 MM X 32 MM 24 X | G<br><br>14 X                 | M3<br><br>Ø 6 MM X 1/2" 20 X | A5<br><br>Ø4 MM X 10 MM 1 X  | V<br><br>1 X                    |
| Q<br><br>FULL OVERLAY 2 X   | S<br><br>3 X                | AE1<br><br>12 X               | AH<br><br>4 X                | AY<br><br>2 X                | AN1<br><br>1 X                  |
| BS<br><br>1 X               | BP1<br><br>1 X              | AA1<br><br>WHITE 3 M          | BR1<br><br>1 X               |   |   |




 X 2  ±45 M

1




2X


3




2




4




5




6




7




8



9




10




13

11




12




14


13




14




15



16



17



18

19

