













ASSEMBLING INSTRUCTION

KUVA SHOWCASE 2D




 BT16 10 X	 BU 1 X	 E1 Ø15 MM X 12 MM 34 X	 B Ø8 MM X 30 MM 39 X	 M1 Ø 4 MM X 5/8" 16 X	 J3 Ø 12 MM X 1 3/4" 16 X
 M Ø 4 MM X 1/2" 3 X	 D Ø6 MM X 32 MM 34 X	 G 16 X	 M3 Ø 6 MM X 1/2" 40 X	 A5 Ø4 MM X 10 MM 2 X	 V 2 X
 L Ø 6 MM X 1 1/2" 12 X	 S 6 X	 AE1 12 X	 AN1 2 X	 Z1 2 X	
 BR1 1 X	 BS 1 X	 BP1 1 X	 AA1 WHITE 3 M	 I 1 X	



X 2


±60 M

03




04


1




2




3



4




5




11

7





8




12

7




8




13

9




10




14

11




12




15

13



2X

14




2X

16


2X

18


19



20



21



22

