






ASSEMBLING INSTRUCTION

ALPHA WORKING DESK 80






 D 7 X Ø12 MM X 10 MM	 E 7 X Ø6 MM X 30 MM	 B1 16 X Ø10 MM X 44 MM	 J1 9 X Ø6 MM X 13 MM	 M3 5 X Ø6 MM X 16 MM	 M6 6 X Ø6 MM X 38 MM
 L 4 X 13 MM	 F 4 g	 W34 1 X 165 MM	 Y 1 SET	 U 1 X Ø16 MM	 BB2 4 X 12 MM

 AT 1 X




 x2 ±45 M 


AT	M3	D	Y	J1	M6	U	L	E	B1	M3	F
											
1X	∅ 6 MM X 13 MM 1X	5X	165 MM 1 SET	∅ 10 MM X 44 MM 1X	∅ 6 MM X 16 MM 2X	∅ 16 MM 1X	∅ 6 MM X 38 MM 4X	∅ 12 MM X 10 MM 2X	∅ 6 MM X 30 MM 2X	∅ 6 MM X 13 MM 4X	13 MM 4 g


D	W34
	
2X	1X

1




2



<p>E</p>  <p>Ø12 MM X 10 MM 5 X</p>	<p>B1</p>  <p>Ø6 MM X 30 MM 14 X</p>	<p>BB2</p>  <p>12 MM 4 X</p>	<p>M6</p>  <p>Ø 6 MM X 16 MM 4 X</p>	<p>J1</p>  <p>Ø 10 MM X 44 MM 8 X</p>
--	---	---	---	--

3



4

