







ASSEMBLING INSTRUCTION

KIVA SHOWCASE 1D




BT16  6 X	BU  1 X	E1  Ø15 MM X 12 MM 24 X	B  Ø8 MM X 30 MM 31 X	M1  Ø 4 MM X 5/8" 14 X	J3  Ø 12 MM X 1 3/4" 14 X
M  Ø 4 MM X 1/2" 2 X	D  Ø6 MM X 32 MM 24 X	G  14 X	M3  Ø 6 MM X 1/2" 20 X	A5  Ø4 MM X 10 MM 1 X	V  1 X
Q  FULL OVERLAY 2 X	S  3 X	AE1  12 X	AH  4 X	AY  2 X	AN1  1 X
BS  1 X	BP1  1 X	AA1  WHITE 3 M	BR1  1 X		




 X 2  ±45 M

1




2X


3




2




4




5




6




7




8



9




10




13

11




12




14

13




14




15

15




16



16

17



18

19

