













ASSEMBLING INSTRUCTION

CHESTER WORKING DESK 120
BLACK OAK





 12 X Ø12 MM X 10 MM	 12 X Ø6 X 30 MM	 12 X Ø10 X 44 MM	 16 X Ø6 MM X 13 MM	 2 X Ø6 MM X 13 MM	 14 X Ø6 MM X 13 MM
 FULL OVERLAY 2 X	 2 X Ø19 MM	 2 X 13 MM	 5 g 350 MM	 R1 R2 L1 L2 1 SET	
 Ø6 MM X 32 MM 4 X	 Ø6 MM X 16 MM 24 X	 1 X	 Ø5 MM X 24 MM 8 X	 Ø9 MM X 13 MM 4 X	

 x2 ±45 M 




1

M3	AT	B	J3	E1
				
Ø 6 MM X 13 MM 3 X	1 X	Ø 6 X 30 MM 1 X	Ø 10 X 44 MM 4 X	Ø 12 MM X 10 MM 4 X





2




03

3

E1	B	J3
		
Ø 12 MM X 10 MM 2 X	Ø 6 X 30 MM 2 X	Ø 10 X 44 MM 4 X






4




04



5


 Ø 5 MM X 24 MM 8 X	 Ø 6 MM X 13 MM 2 X	 Ø 6 X 30 MM 4 X	 Ø 12 MM X 10 MM 4 X	 Ø 10 X 44 MM 8 X
--	--	--	---	--




6



 1 X	 Ø 19 MM 1 X	 Ø 6 MM X 13 MM 5 X	 1 X	 10 X	 FULL OVERLAY 2 X
---	--	--	---	--	--



8




F



13 MM

5 g

U1



Ø19 MM

1 X

V8



1 X


B



Ø6 X 30 MM

5 X

L1



Ø6 MM X 32 MM

4 X

M6



Ø6 MM X 16 MM


20 X

D




2 X

9



10



07


M3



Ø6 MM X 13 MM


4 X

Z1




1 SET

R1



300 MM

R2




L1




L2




11



12





08