



















ASSEMBLING INSTRUCTION

ALPHA WORKING DESK 120




 M3 10 X Ø 6 MM X 13 MM	 W34 2 X	 U 2 X Ø 16 MM	 O1 2 X	 B1 15 X Ø 6 X 30 MM	 J 9 X Ø 10 X 44 MM
 AT 2 X	 Y 1 X Ø 6 MM X 32 MM	 E 7 X Ø 10 MM X 12 MM	 BBY 4 X	 D 7 X	 L 4 X Ø 6 MM X 32 MM
 M6 6 X Ø 6 MM X 16 MM					




 B Ø6 X 30 MM 6 X	 W34 1 X	 U Ø16 MM 1 X	 O1 2 X	 M3 Ø 6 MM X 13 MM 4 X	 E Ø10 MM X 12 MM 1 X	 J Ø 10 X 44 MM 2 X	 AT 1 X	 M3 Ø 6 MM X 13 MM 1 X	 B Ø6 X 30 MM 5 X	 Y Ø 6 MM X 32 MM 1/2 X
---	--	---	--	---	---	--	--	--	---	---


1





2




3






4




M6




J  Ø 10 X 44 MM 7 X	D  4 X	B  Ø 6 X 30 MM 2 X	E  Ø 10 MM X 12 MM 4 X	M6  Ø 6 MM X 16 MM 5 X	Y  Ø 6 MM X 32 MM 1/2 X
--	---	--	--	--	--

5




6





M3  Ø 6 MM X 13 MM 1 X	AT  1 X	D  5 X
---	--	--

7




8



L  4 X	W31  1 X	B  2 X	E  2 X	D  2 X	M3  4 X
Ø 6 MM X 32 MM	Ø 6 X 30 MM	Ø 10 MM X 12 MM	Ø 6 MM X 13 MM	Ø 6 MM X 13 MM	


U




Ø 16 MM

1 X

9



10



11

