








ASSEMBLING INSTRUCTION





KIVA SHOWCASE 2D




 BT16 10 X	 BU 1 X	 E1 34 X <small>Ø15 MM X 12 MM</small>	 B 41 X <small>Ø8 MM X 30 MM</small>	 M1 16 X <small>Ø 4 MM X 5/8"</small>	 J3 16 X <small>Ø 12 MM X 1 3/4"</small>
 M 3 X <small>Ø 4 MM X 1/2"</small>	 D 34 X <small>Ø6 MM X 32 MM</small>	 G 16 X	 M3 40 X <small>Ø 6 MM X 1/2"</small>	 A5 2 X <small>Ø4 MM X 10 MM</small>	 V 2 X
 L 12 X <small>Ø 6 MM X 1 1/2"</small>	 S 6 X	 AE1 12 X	 AN1 2 X	 Z1 2 X <small>300 MM</small>	
 BR1 1 X	 BS 1 X	 BP1 1 X	 AA1 3 M <small>WHITE</small>	 I 1 X	

 X 2  ±60 M







5




6





7




8



7




8




13

9




10




14

11




12




15

13



2X


14



2X



16

15




2X

17




2X

16



2X


18




18

17


19



20



21



22

